

**TABLE OF CONTENTS  
AND  
RECORD OF REVISIONS**

	<b>REVISION</b>	<b>IMPLEMENTATION DATE</b>
Organization and Responsibilities	18	April 28, 2011
Abbreviations and Acronyms	0	May 1, 2001
Quality Control Procedures		
QCP1 Training and Certification	10	May 1, 2001
QCP2 Balance Quality Control	12	August 31, 2011
QCP3 Preparation, Control, and Traceability of Standards	18	December 31, 2010
QCP4 Control of Laboratory Logbooks	13	December 1, 2011
QCP5 Analytical Quality Control and Sample Flow	14	December 1, 2011
QCP6 Radiochemical Contamination Control	10	May 1, 2001
QCP7 Automatic Pipette Quality Control	10	May 1, 2001
QCP8 Counting Room Quality Control	0	May 1, 2001
QCP9 pH Meter Quality Control	0	January 7, 2004
Sample Preparation		
SP1 Sample Screening and Receipt	2	December 1, 2011
SP2 Sample Log-In	1	October 8, 2010
SP3 Sample Preparation	6	June 30, 2009
Analytical Procedures		
AP1 Gross Alpha and Beta for Various Matrices	17	April 28, 2011

**TABLE OF CONTENTS  
AND  
RECORD OF REVISIONS (Continued)**

		<b>REVISION</b>	<b>IMPLEMENTATION DATE</b>
Analytical Procedures (Continued)			
AP2	Determination of Tritium	17	May 28, 2010
AP3	Removed		
AP4	Determination of Total Radiostrontium in Environmental Samples	15	May 28, 2010
AP5	Determination of Technetium-99	18	May 28, 2010
AP6	Determination of Carbon-14 and Tritium Using the Biological Material Oxidizer	18	May 28, 2010
AP7	Determination of Radium-226 in Water and Soil Samples Using Alpha Spectroscopy	19	June 30, 2009
AP8	Radium-228 in Water	5	December 31, 2010
AP9	Determination of Carbon-14 in Water and Smears	4	April 20, 2007
AP10	Analysis of Plutonium-241 in Environmental Samples by Liquid Scintillation Analysis	4	May 28, 2010
AP11	Sequential Determination of the Actinides in Environmental Samples Using Total Sample Dissolution and Extraction Chromatography	5	June 30, 2009
AP12	Determination of Nickel-63 in Environmental Samples	6	June 15, 2007
AP13	Determination of Iron-55 in Water	5	June 15, 2007
AP14	Determination of Sulfur-35 in Solid Environmental Samples	7	June 15, 2007
AP15	Analysis of Polonium-210 in Water, Soil, Air Filters, Miscellaneous Samples, and Biota	1	June 15, 2007
AP16	Determination of Iron-55 in Soil and Other Solid Matrices	1	August 31, 2007

**TABLE OF CONTENTS  
AND  
RECORD OF REVISIONS (Continued)**

	<b>REVISION</b>	<b>IMPLEMENTATION DATE</b>
<b>Counting Procedures</b>		
CP1 Gamma Spectroscopy	17	June 30, 2009
CP2 Alpha Spectroscopy	16	February 28, 2011
CP3 Low Background Alpha/Beta Counter	3	August 31, 2011
CP4 Liquid Scintillation Analyzer (LSA)	4	August 31, 2011
<b>Waste Procedure</b>		
WP1 Waste Generation Procedure	0	May 1, 2001
<b>Appendix A</b>		
Job Hazard Analyses	Various	April 28, 2011
<b>Appendix B</b>		
Minimum Detectable Concentrations of Commonly Reported Radionuclides	0	June 30, 2009

All procedures have been reviewed and approved by:

IEAV Associate Director  
& Director Survey Operations: Erika Bailey for Tim Vitkus Date: 11/30/11

Laboratory Manager: Wade P. Frey Date: 11/30/11

Quality Manager: Ann Templar Date: 11/30/11